

	Proceso UNE-EN ISO 4063:2011	111 (SMAW) (MMA)	131 (GMAW) (MIG)	135 (GMAW) (MAG)	136/137 (FCAW-GS)	141 (GTAW) (TIG)	12 (SAW)	3 (OFW)	51 (EBW)	52 (LBW)	
Preparación de bordes	Aceros	UNE-EN ISO 9692-1:2014					UNE-EN ISO 9692-2:1998 + UNE-EN ISO 9692-2:1998/AC:1999	UNE-EN ISO 9692-1:2014			
	Aluminios		UNE-EN ISO 9692-3:2016			UNE-EN ISO 9692-3:2016					
	Aceros plaqueados	UNE-EN ISO 9692-4:2004									
Soldeo	Materiales metálicos - Guía general	UNE-EN 1011-1:2010									
	Aceros ferríticos	UNE-EN 1011-2:2001 + UNE-EN 1011-2:2001/A1:2005									
	Aceros inoxidables	UNE-EN 1011-3:2001 + UNE-EN 1011-3:2001/A1:2005									
	Aluminios	UNE-EN 1011-4:2001 + UNE-EN 1011-4:2001/A1:2005									
	Aceros plaqueados	UNE-EN 1011-5:2003									
	Soldeo por láser										UNE-EN 1011-6:2006
	Soldeo por haz de electrones									UNE-EN 1011-7:2005	
	Fundición de hierro	UNE-EN 1011-8:2005									